

## Instructions for the View Mode of PamWin-3 Software

1. Download and unzip PamWin-3 setup file.
2. Install PamWin-3 by double-click on PamWin-3 setup file. Default directory for PamWin-3 program is C:\PamWin\_3.
3. Download and unzip sample data (MCPAM\_SampleData.zip). Follow instructions in "MC\_PAM\_SampleDataInstructions.pdf".