

[Linkname: Instructions for Software Use](#)

Instructions for the ViewMode of PamWin-3 Software

1. Download and install PamWin-3 software. By default, PamWin-3 will be installed in directory C:\PamWin_3
2. Download sample data and follow instructions accompanying sample data.
3. Start PamWin-3 software and, when prompted, select PAM-2500.